	Approved For Release 2002/06/24 : CIA-RDP75B00326R000200100023-8
S 17 17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	XERO
-	
(i)	2 July 1963
REPLY TO ATTN OF:	P. B.
SURJECT:	Monthly Activities Report for June 1963
TO:	Commander
101	WRSP-IV
	1. Plight Discrepancies: There were no personal equipment discrepancies
	noted through-out the reporting period.
STATINTL	2. Training: had indoctrinated the Squadron Commander in
•	the use of high altitude personal equipment. The Commander has been
	fitted with a partial pressure suit and helmet for use in subsequent
STATINTL	flight training. had accomplished training in pre-breath-
	ing preparations and assisted in a few pilot suitings. His training is
ů.	progressing slowly due to duty requirements requiring immediate attention.
STATINTL	3. TDY's: TDY to Laughlin AFB and Barkadale AFB from 22 to
1	28 June to provide technical supervisory and/support for BRASS KNOB.
STATINTL	4. leaves: took leave from 10 to 20 June.
	5. Seat Pack Maintenance: In addition to routine seat pack maintenance,
STATINTL	serviced three (3) ARDC seat packs.
	6. Equipment and Material: Transportation: The medical/Personal Equip-
	ment section has been assigned a Chevrolet staff car and a Pontiac ambulance
1 7	to meet the units transportation requirements. The ambulance is being
	considered to eventually replace the P.E. transport truck as the primary.
	transfer vehicle. The P.E. truck will be used as a back up transfer
[8]	vehicle and for TDY's.
STATINTL	Partial Pressure Suits: has had opportunity to thoroughly

COPY

STATINT

A new one has been requisitioned for him and, upon receipt of the new suit, his present back up suit will be returned to David Clark for reconditioning and alterations.

new suit has been determined to be acceptable and a requisition has been submitted for an additional suit. Upon receipt of the second suit, his present back up suit will be returned to the factory for reconditioning and alterations.

Test Equipment: One set of test equipment consisting of an integrator testor and power supply has been losned to the 4080th SRWg OL-19 to be used in testing flight equipment peculair to our aircraft. The test equipment will be returned upon completion of their TDY requirement.

O336 Faceplate: Pive (5) faceplates were loaned to the 4080th SRWg temporarily under the same agreement as the loan of the test equipment.

CMU-1/P Ventilating Garments: Requisitions have been submitted along with SLOE change requests to obtain seven (7) additional ventilating garments. Testing of the garment in conjunction with our requirements reveal the garment will be of considerable help in cooling the pilots in sreas of high temperatures. See Research and Development for further touments.

In Flight Foods Hqs advised, 6 June our requirements for In-flight food tube had been ordered. To date we have not received the food and are at a point where there is only enough on hand to handle one prolonged staging. We are considering increasing our tube food requirements to support the dual staging concept plus provide for routine training flights at the home station.

STATINTL STATINTL

Supply Account:	has	signed	for	the	supply	account	prior	to
av:	ng the organ	ization	•					
Approved For Re	lease 2002/06	/24 : CIA	-RDI	P75E	00326R	00020010	00023-8	ł

7. Research and Development:

STATINTL

STATINTL

a. Has advised that a 35ft canopy parachute and a new seat kit were being shipped to this station for evaluation in our program. To date the equipment has not been received.

the editbment was not been recerved.		
b. Q445 seat pack is presently at a stand still.	checked	STATINTL
into the Q.D. problem while at Laughlin.	reported	STATINTL
numerous malfunctions of the Q.D. had been experienced. One	happended	
while was there. The Personal Equipment technicis	an checked	
the Q.D. for locing before and after the pilot hook-up and i	Lt checked	
out OK. The mobile officer double checked the Q.D. before	closing canopy	STATINTL
and it checked out OK. Then the pilot checked it and it fe	ll out arming	
the emergency oxygen bottle. In checking further with	the	
4080th Flying Safety Officer, and	I was	STATINTL
advised that there were NO problems at all with the new Q.D.	and that the	
discrepancies reported to the undersigned by	not on record	STATINTL
in the Flying Safety Office. The Flying Safety Officer had	nother but go	ood Lood
comments concerning the Q.D. He did say he would look into	the matter	STATINTL
the next time he got together with	s at Laughlin	STATINIL
and was at Barksdale). Your attention is invit-	ed to Persona	
Equipment Report for February 1963, par 9a concerning LAC's	comments	
concerning the Q.D.		

c. Portable Blower and CMU-1/P Ventilating Garment: Three (3)
tests were accomplished utilizing a 28Volt blower motor and a CMU-1/P
Ventilating garment to determine feasibility of providing air circulation
for pilots during transfer of pilot to aircraft and for time while in
aircraft up until closing of canopy. The tests went as follows:
3 Approved For Release 2002/06/24: CIA-RDP75B00326R000200100023-8

Pirst Test: With CMU-1/P Ventilating garment and portable walk around

bottles only. The garment provided sufficient circulation around the torso area when the regulator setting was on "emergency". Oxygen consumption was extremely high, however, and the bottles had to be recharged about ever 2 - 3 minutes. This is considered not practical for field use due to the limited supply of available oxygen.

Second Tests This test was made with the aforementioned ventilating garment, a small 28 V ambient air circulating blower, and the P.E. truck as a power source. The blower worked satisfactorily but a shielded wire was being used and it overheated and the test had to be terminated. Third Tests This test was the same as number two (2) except a new wire was used. And it was used on the pilot after he landed. The test was satisfactory. We are currently looking for utilization of the blower with an electrical source direct from the aircraft. This is being considered due to the different adapters required for utilization with the starting pod, the jeep started, and the MA-2 Start Cart. proposed using an electrical Q.D. that fits the aircraft fan receptacle. A Q.D. is in the process of being obtained and this method will be

8. Personnel: The unit is going to be definitely short of technically qualified Personnel in the forseeable future. will be will be due for release. leaving for discharge just four (4) months there-

checked out as soon as possible.

from the project in May 64, and after. The minimum manning for support of a dual staging concept is going to be affected starting the month of August, and in the event of sickness on the part of one of the remaining technicians, definitely imparired. Trainings The current job profile for the 922 (Personal Approved For Release 2002/06/24: CIA-RDP75B00326R000200100023-8

STATINT

STATINT

STATINT

STATINT

COBA

Equipment) career field with a suffix "B" indicates the individual must be school trained in the use and maintenance of the full pressure suit before the "B" can be awarded. Neigher of the P.E. technicians in this section have been thus trained and should be ASAP in order that the technicians might become current in their specialty.

STATINTL

NCOIC Personal Equipment